

WOID	Description Status Action Taken	Request Date Completion Date	Requester	Assigned To	Location Area Type Area Number
14474	reach in refrigerator behind serving line not holding temp coils have been cleaned off still not working Complete put freon in unit	5/5/2011 5/27/2011	alys casperson	Rascon, Javier	Gateway Elementary School Kitchen 851
14606	the air in my office is not working correctly please fix thanks Complete ran new t-stat wire and installed a new t- stat	5/24/2011 6/6/2011		Rascon, Javier	Gateway Elementary School Custodial
14756	reach in cooler in the cafeteria is reading 44 degrees please check it out when you have time thanks Complete cleaned condensor coil was very dirty and restricting air flow.	6/27/2011 6/30/2011		Rascon, Javier	Gateway Elementary School Cafeteria
14845	welcome center ac is not working correctly please take a look at it it's blowing hot air you have charged this one before thanks Complete put freon in	7/8/2011 8/5/2011		Rascon, Javier	Gateway Elementary School Administration Area
14940	welcome center air you fixed already javier low on freon thanks Complete	8/3/2011 8/5/2011		Rascon, Javier	Gateway Elementary School
15036	Hello, The classroom clock's second hand doesn't work and I use it all the time with students by giving them specifics (i.e."you have 45 seconds to get with a partner") - Can my clock be replaced with one that works please? Thanks! Christina Boston Complete	8/11/2011 8/12/2011	Christina Boston	Rascon, Javier	Gateway Elementary School Classroom 500
15106	ac not working please fix thanks Complete replaced fuses and condensor fan motor	8/19/2011 8/25/2011		Rascon, Javier	Gateway Elementary School Classroom 607
15280	teachers lounge at gateway the ac does not turn on by its self all the time please check it out thanks Complete unit running fine	9/2/2011 9/15/2011		Rascon, Javier	Gateway Elementary School Cafeteria
15387	ac will not turn it self on or off please check out when you get a chance thanks Complete replaced the t-stat	9/19/2011 9/22/2011		Rascon, Javier	Gateway Elementary School Classroom 503
15789	the indoor blower motor is not turning on and causing the indoor coil to ice up please check this out thanks Complete replaced contactor	12/7/2011 12/12/2011		Rascon, Javier	Gateway Elementary School Classroom 701

WOID	Description Status Action Taken	Request Date Completion Date	Requester	Assigned To	Location Area Type Area Number
16269	thanks for following through with replacing the out door fan upon my command signed #2 chop chop Complete By your command.#2	3/21/2012 3/22/2012		Rascon, Javier	Gateway Elementary School Classroom 604
16490	north library unit not working fuse blown one lead going to compressor arched out melted about 1in also part of the wire for the reversing valve New Request	5/15/2012		Rascon, Javier	Gateway Elementary School library
16491	welcome center unit is low on freon is running just not blowing cold New Request	5/15/2012		Rascon, Javier	Gateway Elementary School Administration Area
16650	fix ac New Request	6/19/2012		Rascon, Javier	Gateway Elementary School Classroom 502

Search Results

WOID	Description Status Action Taken	Request Date Completion Date	Requester	Assigned To	Location Area Type Area Number
312	walk-in not working Closed Work Orders	11/15/2005 11/15/2005		Held, David	Gateway Elementary School Kitchen
361	Dave, the freezer has given up, i checked the fuse breaker as well as the unit, everything seems to be on but no fans are working and things are thawing out. Closed Work Orders	11/28/2005 11/30/2005	Rob Bauer	Held, David	Gateway Elementary School Kitchen
388	HVAC #28 not heating front office. unit running and showing heat on, however, discharge air say 47 degrees. office temp at 65 and holding Closed Work Orders	12/1/2005 9/20/2007	Rob Bauer		Gateway Elementary School Administration Area
468	Please have Dave check freezer in Gateway's kitchen reading 35 degrees. Closed Work Orders	12/12/2005 12/15/2005	Angie Marquez	Held, David	Gateway Elementary School Cafeteria Kitchen
795	hvac 611 fan inop, fuse plug blown and filling office with smoke.unit shutdown Closed Work Orders	2/16/2006 2/24/2006	Rob Bauer	Held, David	Gateway Elementary School Administration Area
907	Dave, alys' 'fridge is going down, she has alot of food in there that she is worried about. i looked at the unit on the roof and the motor seems to be frosting up a bit Closed Work Orders	3/9/2006 3/10/2006	Rob Bauer	Held, David	Gateway Elementary School Kitchen
912	Dave, HVAC #849, as per you, inoperative? Closed Work Orders	3/9/2006 3/23/2006	Rob Bauer	Held, David	Gateway Elementary School Multi-purpose Room unit 849
1035	HVAC 302 down, teacher reported to me this morning, that yesterday afternoon, A/C was making a loud sounds then just stopped and room began to get wamer. checked out unit and it will not reset or come back on. I shutdown the power at the unit. Closed Work Orders	3/30/2006 4/4/2006	Rob Bauer	Held, David	Gateway Elementary School Classroom 302
1106	hvac 611 in permanent heat mode, will not cool. checked unit, blowing cool air from fan at top of unit Closed Work Orders	4/11/2006 4/17/2006	Rob Bauer	Held, David	Gateway Elementary School Administration Area

WOID	Description Status Action Taken	Request Date Completion Date	Requester	Assigned To	Location Area Type Area Number
1137	manual thermostat in room 404 not responding to cool command room at 83 and rising, green light illuminated on thermostat, still no cool air Closed Work Orders	4/14/2006 4/18/2006	Rob Bauer	Held, David	Gateway Elementary School Classroom 404
1286	Last week reach in refrigerator not cooling very well (temp at 59), Turned dial colder, to 4, worked for awhile then temp rose again yesterday to 55 degrees, turned to 5 with no results Closed Work Orders	5/11/2006 5/12/2006	Rob Bauer	Held, David	Gateway Elementary School Kitchen
1381	hvac 612, top half of coil iced over Closed Work Orders	5/30/2006 6/2/2006	Rob Bauer	Held, David	Gateway Elementary School Administration Area
1448	Hvac 815 does not seem to be cooling the head in room. checked computer yesterday and it showed offline, reset unit, computer showed online, set room to 71, but it stayed at 82 (with the door open). this morning computer showed online, however, room still very warm (82) Closed Work Orders	6/21/2006 6/22/2006	Rob Bauer	Held, David	Gateway Elementary School Media Center
1531	Dave, HVAC 613 does not seem to be cooling, unit is running but, fan is not rotating, computer says discharge air is 82 degrees Closed Work Orders	7/19/2006 7/19/2006	Rob Bauer	Held, David	Gateway Elementary School Other nurses office
1532	HVAC 861, one of the fans is trying to rotate but is just buzzing. Is this gonna be another summer of love for gateways HVACs? Closed Work Orders	7/19/2006 7/19/2006	Rob Bauer	Held, David	Gateway Elementary School Multi-purpose Room 861
1560	HVAC 204 down, unit completely off. Tried to reset at unit and computer with no luck Closed Work Orders	7/21/2006 7/24/2006	Rob Bauer	Held, David	Gateway Elementary School Classroom 204
1565	HVAC 305 down, tried resetting at unit and computer...nuthin' Closed Work Orders	7/24/2006 7/25/2006	Rob Bauer	Held, David	Gateway Elementary School Classroom 305
1583	just got the call (0745) HVAC 305 down again...checked the fuses but they looked ok Closed Work Orders	7/25/2006 7/25/2006	Rob Bauer	Held, David	Gateway Elementary School Classroom 305
1594	HVAC 200 down Closed Work Orders	7/26/2006 7/26/2006	Rob Bauer	Held, David	Gateway Elementary School Classroom 200

WOID	Description Status Action Taken	Request Date Completion Date	Requester	Assigned To	Location Area Type Area Number
1598	Hvac 207 will not cool, room very humid. computer show discharge air @ 76 degrees. fan on roof blowing semi cool air. i could set you up with a nice office here! Closed Work Orders	7/26/2006 7/26/2006	Rob Bauer	Held, David	Gateway Elementary School Classroom 207
1641	Hvac 602, when cooling the room, air comes on very hot and slowly changes to cool (approx 8-10 min) when room is in fact cool(?), room is very humid Closed Work Orders	8/2/2006 8/4/2006	Rob Bauer	Held, David	Gateway Elementary School Classroom 602
1710	its your best customer! Sorry to have to report HVAC 207 again. Room very hot, discharge air @ 94 degrees, once again, reset unit with no change Closed Work Orders	8/10/2006 8/23/2006	Rob Bauer	Held, David	Gateway Elementary School Classroom 207
1834	Dave, the reach in fridge closest to alys's office is on thr blink, cleaned the coil and turned up the 'stat but it still reads 45 degrees Closed Work Orders	8/28/2006 8/30/2006	Rob Bauer	Held, David	Gateway Elementary School Kitchen
1877	Dave, the Gateway office A/C is acting up again (HVAC611)this morning it was working ok(I reset the unit), however, in the afternoon(s) it quits cooling. Suzie asked if you would take a look at it Closed Work Orders	9/6/2006 9/8/2006	Rob Bauer	Held, David	Gateway Elementary School Administration Area
1917	HVAC 612 (welcome center) not cooling. Discharge air reads 68 degrees but room temp @ 81 Closed Work Orders	9/13/2006 10/3/2006	Rob Bauer	Held, David	Gateway Elementary School Administration Area welcome center
1972	Dave, the temp on one of the reach in 'fridges @ Gateway is on the rise again Closed Work Orders	9/27/2006 10/2/2006	Rob Bauer	Held, David	Gateway Elementary School Kitchen
1990	mens staff restroom toilet only flushes when you push in and hold handle Closed Work Orders replaced parts	10/4/2006 10/9/2006	Rob Bauer	Johnson, Scott	Gateway Elementary School Restroom
2027	Please have Dave check and repair the ice machine at GW. It is totally shut down. Thanks Dawn =) Closed Work Orders	10/17/2006 10/17/2006	Dawn Brees	Held, David	Gateway Elementary School kitchen
2310	Dave, HVAC 611 does not seem to be heating the office. computer says unit is on an heating, but the discharge temp says 62. Went up and shut the unit down for 5 min, it came back on but the fan did not start Closed Work Orders	1/8/2007 1/12/2007	Rob Bauer	Held, David	Gateway Elementary School Administration Area

WOID	Description Status Action Taken	Request Date Completion Date	Requester	Assigned To	Location Area Type Area Number
2311	Dave, this HVAC also went down over the break (HVAC 816), however its not high on the priority list since its the hallway. Computer says its off, and its correct, went up and tried to reset it, but it never would come on Closed Work Orders	1/8/2007 1/16/2007	Rob Bauer	Held, David	Gateway Elementary School Hallway/Corridor
2341	HVAC 202 will not produce any heat, computer says heat is on but discharge air says 61 degrees Closed Work Orders	1/16/2007 1/17/2007	Rob Bauer	Held, David	Gateway Elementary School Classroom 202
2343	HVAC 610 has also decided not to put out any heat, computer says heat is on but discharge air says 37 degrees Closed Work Orders	1/16/2007 1/17/2007	Rob Bauer	Held, David	Gateway Elementary School Hallway/Corridor
2365	Sorry Dave, HVAC 202 still not heating up room. I know you looked at it yesterday, but the teachers came to me again this morning cause it was 65 degrees in there and the kids were freezing. I couldnt get it any warmer Closed Work Orders	1/18/2007 1/23/2007	Rob Bauer	Held, David	Gateway Elementary School Classroom 202
2420	Dave, one of the reach in refridgerators temp is on the rise, its at 59 right now. yesterday i turned it to the coldest point with no results Closed Work Orders 6.18.07: Fax to Pete @ School Equipment. Repaired & lubed; no replacement parts needed.	1/30/2007 8/27/2007	Rob Bauer	Held, David	Gateway Elementary School Kitchen
2518	Please have Dave check the temperature gauge on the walk-in freezer @GW. It is not recording the temperature correctly. See Alys for more info. Thanks Dawn =) Closed Work Orders	2/15/2007 2/21/2007	Dawn Brees	Held, David	Gateway Elementary School Kitchen kitchen
2584	HVAC 405 not heating room, will only provide arctic like conditions Closed Work Orders	2/28/2007 3/5/2007	Rob Bauer	Held, David	Gateway Elementary School Classroom HVAC 405
2920	Hvac 600 does not seem to be cooling the room, room is around 80 degrees Closed Work Orders	4/17/2007 4/23/2007	Rob Bauer	Held, David	Gateway Elementary School Classroom 600
2995	Please have Dave check the freezer at GW asap it is down. Thanks Dawn =) Closed Work Orders	4/30/2007 5/2/2007	Dawn Brees	Held, David	Gateway Elementary School Kitchen kitchen

8-23-06

Roy Sucanik
Director of Physical Plant Services
Creighton School District

RE: 5 Ton Package Heat Pump Replacement

We are pleased to propose the following:

- Remove and dispose of existing unit
- Install new Carrier 50HJQ006 5 ton package heat pump utilizing a custom curb adapter on the existing roof curb to transition to new unit
- Connect to existing electrical
- Connect copper condensate to existing
- Start up and test operation

For the sum of \$6,220.00 plus applicable tax

We look forward to providing this service for your district. Please feel free to contact me should you have any questions.

Sincerely,

Chance Jondahl
Estimation Dept.

School: Gateway Elementary

Bldg Designation	Manufacturer/Model No.	Type of Cooling/Heating	Yr Installed	Condition	EMS	Replacement Date	Date Replaced	Cost
Main Building								
Bldg A Room #200	Carrier – 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #201	Carrier – 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #202	Carrier – 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #203	Carrier – 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #204	Carrier – 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #205	Carrier – 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #206	Carrier – 6 ton #50TJQ0007-611	Heat Pump	1998	Good	Yes	2015		\$ 4,507.20
Bldg A Room #207	Carrier – 6 ton #50TJQ0007-611	Heat Pump	1998	Good	Yes	2015		\$ 4,507.20
Bldg A Room #208	Carrier – 3 ton #50HJQ0004-601	Heat Pump	1998	Good	Yes	2015		\$ 3,035.00
Bldg A Room #209	Carrier – 6 ton #50TJQ0007-611	Heat Pump	1998	Good	Yes	2015		\$ 4,507.20
Bldg B Room #301	Carrier – 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg B Room #302	Carrier – 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00

Bldg Designation	Manufacturer/Model No.	Type of Cooling/Heating	Yr Installed	Condition	EMS	Replacement Date	Date Replaced	Cost
Bldg B Room #303	Carrier - 4 ton #50HJQ005-601	Heat Pump	1998	Good	Yes	2015		\$ 3,674.25
Bldg B Room #304	Carrier - 5 ton #50HJQ006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg B Room #305	Carrier - 4 ton #50HJQ005-601	Heat Pump	1998	Good	Yes	2015		\$ 3,674.25
Bldg A Room #400	Carrier - 5 ton #50HJQ006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #401	Carrier - 4 ton #50HJQ005-601	Heat Pump	1998	Good	Yes	2015		\$ 3,674.25
Bldg A Room #402	Carrier - 5 ton #50HJQ006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #403	Carrier - 4 ton #50HJQ005-601	Heat Pump	1998	Good	Yes	2015		\$ 3,674.25
Bldg A Room #404	Carrier - 6 ton #50TJQ007-611	Heat Pump	1998	Good	Yes	2015		\$ 4,507.20
Bldg A Room #405	Carrier - 5 ton #50HJQ006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #406	Carrier - 2 ton #50HX-024-311	Heat Pump	1998	Good	Yes	2015		\$ 2,800.00
Bldg B Room #500	Carrier - 5 ton #50HJQ006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg B Room #501	Carrier - 5 ton #50HJQ006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg B Room #502	Carrier - 6 ton #50TJQ007-611	Heat Pump	1998	Good	Yes	2015		\$ 4,507.20

Bldg Designation	Manufacturer/Model No.	Type of Cooling/Heating	Yr Installed	Condition	EMS	Replacement Date	Date Replaced	Cost
Bldg B Room #503	Carrier - 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg B Room #504	Carrier - 3 ton #50HJQ0004-601	Heat Pump	1998	Good	Yes	2015		\$ 3,035.00
Bldg B Room #505	Carrier - 2 ton #50HX-024-311	Heat Pump	1998	Good	Yes	2015		\$ 2,800.00
Bldg B Room #506	Carrier - 6 ton #50TJQ0007-611	Heat Pump	1998	Good	Yes	2015		\$ 4,507.20
Bldg B Room #507	Carrier - 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg B Room #508	Carrier - 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg B Room #509	Carrier - 5 ton #50HJQ0006-601	Heat Pump	1958	Poor	Yes	2015		\$ 4,260.00
Bldg A Room #600	Carrier - 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #601	Carrier - 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #602	Carrier - #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #603	Carrier -4 ton #50HJQ0005-601	Heat Pump	1998	Good	Yes	2015		\$ 3,674.25
Bldg A Room #604	Carrier - 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #605	Carrier - 4 ton #50HJQ0005-601	Heat Pump	1998	Good	Yes	2015		\$ 3,674.25

Bldg Designation	Manufacturer/Model No.	Type of Cooling/Heating	Yr Installed	Condition	EMS	Replacement Date	Date Replaced	Cost	
Bldg A Room #606	Carrier - 7 1/2 #50HJQ008-601	Heat Pump	1998	Good	Yes	2015		\$ 6,993.50	
Bldg A Room #607	Carrier - 5 ton #50HJQ006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00	
Bldg A Room #608	Carrier - 6 ton #50TJQ007-611	Heat Pump	1998	Good	Yes	2015		\$ 4,507.20	
Bldg A Room #609	Carrier - 3 ton #50HJQ004-601	Heat Pump	1998	Good	Yes	2015		\$ 3,035.00	
Bldg A Room #610	Carrier - 4 ton #50HJQ005-601	Heat Pump	1998	Good	Yes	2015		\$ 3,674.25	
Bldg A Room #611	Carrier - 6 ton #50TJQ007-611	Heat Pump	1998	Good	Yes	2015		\$ 4,507.20	
Bldg A Room #612	Carrier - 6 ton #50TJQ007-611	Heat Pump	1998	Good	Yes	2015		\$ 4,507.20	
Bldg A Room #613	Carrier - 4 ton #50HJQ005-601	Heat Pump	1998	Good	Yes	2015		\$ 3,674.25	
Bldg A Room #614	Carrier - 4 ton #50HJQ005-601	Heat Pump	1998	Good	Yes	2015		\$ 3,674.25	
Bldg B Room #700	Carrier - 5 ton #50HJQ006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00	
Bldg B Room #701	Carrier - 4 ton #50HJQ005-601	Heat Pump	1998	Good	Yes	2015		\$ 3,674.25	
Bldg B Room #702	Carrier - 5 ton #50HJQ006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00	
Bldg B Room #703	Carrier - 5 ton #50HJQ006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00	

Bldg Designation	Manufacturer/Model No.	Type of Cooling/Heating	Yr Installed	Condition	EMS	Replacement Date	Date Replaced	Cost
Bldg B Room #704	Carrier - 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #801	Carrier - 7 1/2 ton #50TJQ0008-601	Heat Pump	1998	Good	Yes	2015		\$ 6,993.50
Bldg A Room #803	Carrier - 3 ton #50HJQ0004-601	Heat Pump	1998	Good	Yes	2015		\$ 3,035.00
Bldg A Room #804	Carrier - 6 ton #50TJQ0007-611	Heat Pump	1998	Good	Yes	2015		\$ 4,507.20
Bldg A Room #805	Carrier - 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #806	Carrier - 4 ton #50HJQ0005-601	Heat Pump	1998	Good	Yes	2015		\$ 3,674.25
Bldg A Room #807	Carrier - 7 1/2 ton #50TJQ0008-601	Heat Pump	1998	Good	Yes	2015		\$ 6,993.50
Bldg A Room #808	Carrier - 3 ton #50HJQ0004-601	Heat Pump	1998	Good	Yes	2015		\$ 3,035.00
Bldg A Room #813	Carrier - 6 ton #50TJQ0007-611	Heat Pump	1998	Good	Yes	2015		\$ 4,507.20
Bldg A Room #814	Carrier - 5 ton #50HJQ0006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00
Bldg A Room #815	Carrier - 4 ton #50HJQ0005-601	Heat Pump	1998	Good	Yes	2015		\$ 3,674.25
Bldg A Room #816	Carrier - 6 ton #50TJQ0007-611	Heat Pump	1998	Good	Yes	2015		\$ 4,507.20
Bldg C Room #847	Carrier - 7 1/2 ton #50TJQ0008-601	Heat Pump	1998	Good	Yes	2015		\$ 6,993.50

Bldg Designation	Manufacturer/Model No.	Type of Cooling/Heating	Yr Installed	Condition	EMS	Replacement Date	Date Replaced	Cost	
Bldg C Room #848	Carrier – 7 ½ ton #50TJQ008-601	Heat Pump	1998	Good	Yes	2015		\$ 6,993.50	
Bldg C Room #849	Carrier – 10 ton #50TJQ012-601	Heat Pump	1998	Good	Yes	2015		\$ 9,500.00	
Bldg C Room #850	Carrier – 10 ton #50TJQ012-601	Heat Pump	1998	Good	Yes	2015		\$ 9,500.00	
Bldg C Room #851	Carrier – 10 ton #50TJQ012-601	Heat Pump	1998	Good	Yes	2015		\$ 9,500.00	
Bldg C Room #852	Carrier – 5 ton #50HJQ006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00	
Bldg C Room #853	Carrier – 4 ton #50HJQ005-601	Heat Pump	1998	Good	Yes	2015		\$ 3,674.25	
Bldg C Room #855	Carrier – 5 ton #50HJQ006-601	Heat Pump	1998	Good	Yes	2015		\$ 4,260.00	
Bldg C Room #856	Carrier – 6 ton #50TJQ007-611	Heat Pump	1998	Good	Yes	2015		\$ 4,507.20	
Bldg C Room #857	Carrier – 6 ton #50TJQ007-611	Heat Pump	1998	Good	Yes	2015		\$ 4,507.20	
Bldg C Room #858	Carrier – 7 ½ ton #50TJQ008-601	Heat Pump	1998	Good	Yes	2015		\$ 6,993.50	
Bldg C Room #859	Carrier – 6 ton #50TJQ007-611	Heat Pump	1998	Good	Yes	2015		\$ 4,507.20	
Bldg C Room #860	Carrier – 3 ton #50HJQ004-601	Heat Pump	1998	Good	Yes	2015		\$ 3,035.00	
Bldg C Room #861	Carrier – 10 ton #50TJQ012-601	Heat Pump	1998	Good	Yes	2015		\$ 9,500.00	

Bldg Designation	Manufacturer/Model No.	Type of Cooling/Heating	Yr Installed	Condition	EMS	Replacement Date	Date Replaced	Cost
Bldg C Room #862	Carrier - 10 ton #50TJQ012-601	Heat Pump	1998	Good	Yes	2015		\$ 9,500.00
Bldg C Room #863	Carrier - 3 ton #50HJQ004-601	Heat Pump	1998	Good	Yes	2015		\$ 3,035.00
Bldg C Room #864	Carrier - 10 ton #50TJQ012-601	Heat Pump	1998	Good	Yes	2015		\$ 9,500.00
Bldg C Room #865	Carrier - 4 ton #50HJQ005-601	Heat Pump	1998	Good	Yes	2015		\$ 3,674.25